

From: [Halasz, Stephen \(Austin, TX-US\)](#)
To: [Gary Moore/R6/USEPA/US@EPA](#)
Cc: [Richard Bergner](#); [Jonathan Carroll](#); [Arredondo, Alonzo](#)
Subject: Falcon Refinery
Date: 03/12/2012 10:26 AM

Gary,

Last week Bob Swaim of BBB Tank Services, Inc. was at the Falcon Refinery and performed an assessment of the Tanks that are a part of the Removal Action. His comments are below:

Tank 7, is savable, will need new skin on roof, new floor will more than likely be needed, hand rails will need work about 25 stair treads will needed to be replaced, if new floor nozzles will have to be redone, do not know if this tank has an IFR or not.

Tank 26, will need new roof and structure, new stair treads, ladder landing, new floor, nozzles relocated per API. And an aluminum IFR.

Tank 12 will need a new cone roof and most all structure will be needed to be replaced, new IFR (aluminum) 15 stair treads will have to be replaced, ladder landing will have to be replaced, new floor and relocate nozzles. Tank still has 6 to 8" of water and light product inside, aluminum roof is down on floor.

We will work with Lazarus Energy and BBB to complete the required actions of the Removal Action especially on the coordination of Tank 12.

Stephen Halasz
Program Manager

505 East Huntland Drive, Suite 250, Austin TX 78750
T: 512.684.3351 | F: 512.329.8750 | C: 512.745.6155



Follow us on [LinkedIn](#) or [Twitter](#) | www.trcsolutions.com

***** ATTACHMENT NOT DELIVERED *****

This Email message contained an attachment named
image001.jpg
which may be a computer program. This attached computer program could
contain a computer virus which could cause harm to EPA's computers,
network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced
into the EPA network. EPA is deleting all computer program attachments
sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you
should contact the sender and request that they rename the file name
extension and resend the Email with the renamed attachment. After
receiving the revised Email, containing the renamed attachment, you can
rename the file extension to its correct name.

For further information, please contact the EPA Call Center at
(866) 411-4EPA (4372). The TDD number is (866) 489-4900.

***** ATTACHMENT NOT DELIVERED *****



9567122